


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Aug 20, 2024 at 9:19:59 AM
CO



Aug 20, 2024 at 9:24:31 AM
CO

Photo # 5469 From entrance to location

Photo # 5470 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5471 Location



Photo # 5472 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5473 Location



Photo # 5474 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5475 Location



Photo # 5476 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5477 Stored camper on location



Photo # 5478 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5479 Debris



Photo # 5480 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5481 Tank label weathered & some required info is illegible



Photo # 5482 Wellhead signs weathered & cracking/starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Burchfield RWF 44-32 Pad

Location ID: 416774



Photo # 5483 Wellhead signs weathered & cracking/starting to become illegible



Photo # 5484 Wellhead signs weathered & cracking/starting to become illegible