

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Location Entrance – Photo #02875



Wellhead – Photo #02876

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Wellhead – Photo #02877



Wellhead – Photo #02889

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Gas Meters – Photo #02879



Gas Lift – Photo #02883

Inspection Photos


Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Gas Lift – Photo #02885



Gas Lift – Photo #02887

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Tank Battery – Photo #02880



Corrosion in Tank Wall – Photo #02891

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/EF G29 595

Location ID: 335573

Date: 8/14/2024



Corrosion in Tank Wall – Photo #02892



Production to Unserviceable Blowdown Tank – Photo #02893