

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2024

Submitted Date:

08/20/2024

Document Number:

708302607

FIELD INSPECTION FORMLoc ID 335573 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274028	WELL	PR	12/01/2023	GW	045-10314	N. PARACHUTE EF07D H29 595	PR
282093	WELL	PR	02/01/2014	GW	045-11655	N.PARACHUTE EF 16B G29 595	PR
282099	WELL	PR	11/13/2006	GW	045-11653	N.PARACHUTE EF 16D G29 595	PR
282100	WELL	PR	11/09/2006	GW	045-11652	N.PARACHUTE EF01B G29 595	PR
282101	WELL	PR	11/13/2006	GW	045-11651	N.PARACHUTE EF09B G29 595	PR
282108	WELL	PR	09/20/2006	GW	045-11661	N. PARACHUTE EF06D G29 595	PR
282109	WELL	PR	09/21/2006	GW	045-11660	N. PARACHUTE EF07B G29 595	PR
282110	WELL	PR	12/14/2005	GW	045-11659	N.PARACHUTE EF 15B G29 595	PR
282111	WELL	PR	11/09/2006	GW	045-11658	N.PARACHUTE EF 15D G29 595	PR
282112	WELL	PR	12/14/2005	GW	045-11657	N.PARACHUTE EF 14D G29 595	PR
282113	WELL	SI	05/01/2024	GW	045-11656	N PARACHUTE EF02B-32 G29 595	SI
282134	WELL	PR	08/20/2006	GW	045-11679	N.PARACHUTE EF 10B G29 595	PR
282135	WELL	PR	08/23/2006	GW	045-11680	N.PARACHUTE EF11D G29 595	PR
289622	WELL	PR	09/01/2022	GW	045-13844	N.PARACHUTE EF02D G29 595	PR

289623	WELL	PR	08/26/2008	GW	045-13843	N.PARACHUTE EF08D G29 595	PR
289624	WELL	PR	08/26/2008	GW	045-13842	N.PARACHUTE EF08B G29 595	PR
289625	WELL	PR	08/10/2008	GW	045-13841	N.PARACHUTE EF03B G29 595	PR
289626	WELL	PR	03/07/2007	GW	045-13840	N. PARACHUTE EF10D G29 595	PR
289627	WELL	PR	02/01/2014	GW	045-13839	N.PARACHUTE EF09D G29 595	PR
289628	WELL	PR	08/15/2008	GW	045-13838	N.PARACHUTE EF02B G29 595	PR
291027	WELL	SI	04/01/2024	GW	045-14260	N.PARACHUTE EF 12B G29 595	SI
419810	WELL	PR	08/12/2011	GW	045-20025	N. Parachute DH05-20 G29 595	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 8/14/2024 at approximately 13:35, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. Parachute/EF G29 595 at Location ID #335573 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Corrosion and holes present on tank wall of blowdown tank. Tank is marked as 'Out of Service' but is in-service and lined up to N.PARACHUTE #EF 14D G29, API: 595 05-045-11657.

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [911/\(970\)285-2615](#)

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Gas meters/lift protected by concrete barriers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas Lift		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:	Corrosion and holes present on tank walls. Tank is labeled as 'Out of Service' but is lined up to production.					
Corrective Action:	Maintain, repair, or replace tank to comply with Rule 609.b.					Date: 09/19/2024

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	274028	Type:	WELL	API Number: 045-10314 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282093	Type:	WELL	API Number: 045-11655 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282099	Type:	WELL	API Number: 045-11653 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282100	Type:	WELL	API Number: 045-11652 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282101	Type:	WELL	API Number: 045-11651 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282108	Type:	WELL	API Number: 045-11661 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282109	Type:	WELL	API Number: 045-11660 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282110	Type:	WELL	API Number: 045-11659 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 282111 Type: WELL API Number: 045-11658 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 282112 Type: WELL API Number: 045-11657 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 282113 Type: WELL API Number: 045-11656 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:

Comment: Last produced April 2024 per production report.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 282134 Type: WELL API Number: 045-11679 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 282135 Type: WELL API Number: 045-11680 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289622 Type: WELL API Number: 045-13844 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289623 Type: WELL API Number: 045-13843 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289624 Type: WELL API Number: 045-13842 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289625 Type: WELL API Number: 045-13841 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289626 Type: WELL API Number: 045-13840 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289627 Type: WELL API Number: 045-13839 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289628 Type: WELL API Number: 045-13838 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291027 Type: WELL API Number: 045-14260 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: Last produced March 2024 per production report.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419810 Type: WELL API Number: 045-20025 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Gravel						
		Gravel				
Compaction						
		Culverts				
		Compaction				
Berms						
		Ditches				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302608	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672558