

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2024

Submitted Date:

08/20/2024

Document Number:

699506203

FIELD INSPECTION FORMLoc ID 449176 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449175	WELL	SI	03/01/2024	OW	001-10003	King 3-65 28-29 3AH	SI
449176	LOCATION	AC	05/08/2024		-	King 3-65 28-29	AC
458413	WELL	SI	03/01/2024	OW	001-10224	King 3-65 28-29 3DH	SI
458414	WELL	SI	03/01/2024	OW	001-10225	King 3-65 28-29 3CH	SI
458415	WELL	SI	03/01/2024	OW	001-10226	King 3-65 28-29 3BH	SI
486009	WELL	DG	05/08/2024		001-10557	Bear 3-65 22-23 4BH	DG
486034	WELL	DG	05/01/2024		001-10558	Florida 3-65 27-26 1AH	DG
486035	WELL	DG	04/30/2024		001-10559	Florida 3-65 27-26 1BH	DG
486036	WELL	DG	04/29/2024		001-10560	Florida 3-65 27-26 2AH	DG
486037	WELL	DG	04/28/2024		001-10561	Florida 3-65 27-26 4AH	DG
486038	WELL	DG	04/27/2024		001-10562	Florida 3-65 27-26 4BH	DG
486039	WELL	DG	05/07/2024		001-10563	King 3-65 28-29- 1AH	DG
486040	WELL	DG	05/06/2024		001-10564	King 3-65 28-29 1BH	DG
486041	WELL	DG	05/05/2024		001-10565	King 3-65 28-29 2AH	DG
486042	WELL	DG	05/04/2024		001-10566	King 3-65 28-29 2BH	DG
486043	WELL	DG	05/03/2024		001-10567	King 3-65 28-29 4AH	DG
486044	WELL	DG	05/02/2024		001-10568	King 3-65 28-29 4BH	DG

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 449175 Type: WELL API Number: 001-10003 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 449176 Type: LOCATION API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 458413 Type: WELL API Number: 001-10224 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 458414 Type: WELL API Number: 001-10225 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 458415 Type: WELL API Number: 001-10226 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486009 Type: WELL API Number: 001-10557 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486034 Type: WELL API Number: 001-10558 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: 7922 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: At time of inspection frac crew was in process of hydraulic fracture of Florida 1AH well.
Injection pressure at time of inspection was 7922.

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486035 Type: WELL API Number: 001-10559 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486036 Type: WELL API Number: 001-10560 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486037 Type: WELL API Number: 001-10561 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486038 Type: WELL API Number: 001-10562 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486039 Type: WELL API Number: 001-10563 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486040 Type: WELL API Number: 001-10564 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	486041	Type:	WELL	API Number:	001-10565	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	486042	Type:	WELL	API Number:	001-10566	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	486043	Type:	WELL	API Number:	001-10567	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	486044	Type:	WELL	API Number:	001-10568	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were Hot, clear, light wind.	medinaj	08/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506204	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672898