

Inspection Photos

API: 017-06622

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. The cattleguard at the beginning of the access road has been cleaned out and the material was removed.



Inspection Photos



Photo 2. Facing southeast along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 3. Facing southeast along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 4. Facing east toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06622 | Date: 8/19/2024

Inspection Photos



Photo 5. There is still stained soils around the wellhead from a E&P waste spill. It appears there was sand spread on top of the spill which was not cleaned up per the rules. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 8/19/2024

Inspection Photos



Photo 6. This chemical drum has no secondary containment and has been leaking fluids onto the soils which are stained.



Inspection Photos



Photo 7. Further out from the well just a few inches below the surface was oil stained soils with a hydro carbon odor. All impacted soils must be cleaned up and removed.



Inspection Photos



Photo 8. North side of the location facing south. There appears to be impacts to vegetation from a suspected previous spill that flowed downhill to this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 9. There are chemical barrels with no secondary containment. There is fresh sand spread around the pumpjack where oil staining was previously observed.



Inspection Photos



Photo 10. Facing at the backside of the pumpjack where exhaust is located. There is a bucket of oil at red arrow that is about to spill over. There is stained soils around the pumpjack engine that is still leaking. There is oil stained soils at the engine exhaust pipe.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 8/19/2024

Inspection Photos



Photo 11. Facing at the south side of the pumpjack. There is oil stained soils shown at the red arrows.



Inspection Photos



Photo 12. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06622 | Date: 8/19/2024