

Inspection Photos

API: 017-06629

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06629 | Date: 8/19/2024

Inspection Photos



Photo 2. Facing northeast toward the location. There are no guyline markers installed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. There is a pile of oily rags at the south side of the location. This must be removed and properly disposed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing toward the pumpjack engine. There was new sand spread around the pumpjack base to cover up the stained soils which were not cleaned up. There are three cans of starting fluid and the blue can that need to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06629 | Date: 8/19/2024

Inspection Photos



Photo 5. Facing northwest toward the wellsite. The red arrow points to an oily rag.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. The pumpjack engine is still leaking oil.



Inspection Photos



Photo 7. It appears there was sand spread on top of the spill which was not cleaned up per the rules. There is still oily soils that remain underneath the sand that was placed over the stained soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06629 | Date: 8/19/2024

Inspection Photos



Photo 8. There is impacted soils about 15 ft. north of the pumpjack engine.



Inspection Photos



Photo 9. There is oily fluid in the secondary containment and no wildlife protection/netting is installed. The labeling on the barrels is faded and needs to be updated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06629 | Date: 8/19/2024

Inspection Photos



Photo 10. Facing toward the wellhead. There are stained soils by the wellhead shown at red arrow.



Inspection Photos



Photo 11. Scratching the soils by the wellhead show oily saturated black staining from E&P waste.

