

Inspection Photos

API: 017-06636

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06636 | Date: 8/19/2024

Inspection Photos



Photo 2. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06636 | Date: 8/19/2024

Inspection Photos



Photo 3. Facing west along the road toward the wellsite. There has been gravel spread along the area where erosion channel was previously observed.



Inspection Photos




Photo 4. Facing west toward the wellsite. There are oily rags/gloves in this area that must be disposed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. View of stained soils and oily gloves.



Inspection Photos



Photo 6. Facing toward the wellhead. The barrel is not properly set in the containment and there is no netting on the secondary containment..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06636 | Date: 8/19/2024

Inspection Photos




Photo 7. Facing toward the electric utility just south of the well. The electric wire is on the surface and not protected which is a safety concern. The electric breaker is disconnected from the electric line.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources