

Inspection Photos

API: 017-06632

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. The access road was inaccessible due to water pooling on the road. The road needs to be built up with road base to allow proper stormwater drainage. Photo from previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06632 | Date: 8/19/2024

Inspection Photos



Photo 2. Facing southeast along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road



boundary
COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06632 | Date: 8/19/2024

Inspection Photos



Photo 3. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06632 | Date: 8/19/2024

Inspection Photos



Photo 4. Facing northeast toward the pumpjack. There is an oily rag at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. There is oily fluids in the red container that are about to overtop and spill on the ground.



Inspection Photos



Photo 6 . Facing northwest at the pumpjack. There are stained soils at red arrow and parts laying on the ground.

