

Inspection Photos

API: 017-06502

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. Facing at the pumpjack. The gate was left open and livestock entered in the enclosure. The well sign on the gate is obstructed from view.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06502 | Date: 8/19/2024

Inspection Photos



Photo 3. The chemical barrel has tipped over and there are signs that livestock was inside this enclosure. There is oil stained soils at the wellhead.



Inspection Photos



Photo 4. The guyline anchors are not marked.

