

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

713601343**FIELD INSPECTION FORM**Loc ID 321625 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Storts, Doug		pds@willifordenergy.com	
GROWNS LARRY		lgrowns@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207567	WELL	PR	01/01/2023	GW	017-06502	RHOADES UNIT 4-2	RI

General Comment:

This is a location inspection of the RHOADES Unit #4-2 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Guy line anchors are not marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	09/07/2024

Emergency Contact Number:

Comment:	The well sign is installed at the gate which is not visible when the gate is left open. Sign needs to be posted in a visible area at the wellhead.		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	There is a chemical barrel that has tipped over at the wellhead that must be removed or properly secured to prevent leakage.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention.	Date:	08/30/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	There are oil stained soils at the wellhead that must be cleaned up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:	08/30/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	The gate was left open and livestock entered in at the wellhead. Gate must be kept closed to prevent livestock entry.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601344	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673246