

**Inspection Photos**  
**Location Name:** RUFF-66N64W/3SEW  
**Location #:** 305536



**Photo #1**

**Ruff 22-3 (123-23107) Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plug(s)**



**Photo #2**

**Ruff 22-3 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plug(s)**  
*Site safety signage*





**Inspection Photos**  
**Location Name: RUFF-66N64W/3SENW**  
**Location #: 305536**



**Photo #3**  
**Ruff 22-3 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plug(s)**  
*Wellsite entrance*

**Photo #4**  
**Ruff 22-3 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plug(s)**  
**JSA: 2024-08-20**



**Inspection Photos**  
**Location Name:** RUFF-66N64W/3SENW  
**Location #:** 305536



**Photo #5**

**Ruff 22-3 Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Initial plug(s)**

*Wellsite sign*



**COLORADO**  
**Energy & Carbon Management  
Commission**  
Department of Natural Resources