

Inspection Photos

API: 017-06652

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the beginning of the access road. The cattleguard will need to be removed and fence installed back to original position. The road needs to be reclaimed.



Inspection Photos



Photo 2. Facing west along the access road. This portion of the road has revegetated.



Inspection Photos



Photo 3. Facing northwest at the location. The cut slope has not been recontoured back to the original terrain contours.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing toward the cut slope that has not been recontoured back to the original terrain contours.



Inspection Photos



Photo 5. Facing south at the top of the cut slope. There is a berm along the top of the which needs to be recontoured along the cut slope



Inspection Photos



Photo 6. Facing southwest at the top of the cut slope. There is a berm along the top of the which needs to be recontoured along the cut slope



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing southeast at the top of the cut slope. There is a berm along the top which needs to be recontoured along the cut slope.



Inspection Photos



Photo 8. West side of the location facing east.



Inspection Photos



Photo 9. Facing north toward the surrounding undisturbed reference area.

