

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

707603116**FIELD INSPECTION FORM**Loc ID 330538 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251454	WELL	SI	05/01/2021	OW	123-19257	SLW GREEN STATE BB 18 -09	PA

General Comment:This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING inspection.**

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing; Base plug.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.396256 / -104.478884

Well GPS coordinates: 40.397159 / -104.473185

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	OTHER			
Comment:	Jobsite entrance & safety signage posted.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	251454	Type:	WELL	API Number:	123-19257	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name:		JMR Services, LLC		Contractor Phone:					
Surface Casing									
Cement Volume (sx):				Circulate to Surface:					
Cement Fall Back:				Top Job, 1" Volume:					
Intermediate Casing									
Cement Volume (sxs):				Good Return During Job:					
Production Casing									
Cement Volume (sx):				Good Return During Job:					
Plugging Operations									
Depth Plugs(feet range):		1510'-1402'		Cement Volume (sx):		35 sxs			
Good Return During Job:				Cement Type:		Ethixo 15.2#			
Comment:		<div>2024/08/19: Plugging Operations: Cementing; Base plug. 2024/08/19: JSA attached as photo to this report. Workover Contractor: JMR Services, LLC Rig #12. Cement Contractor: JMR Services, LLC. SAFETY/JSA MEETING. SWC/SYLA, LOCK/OUT TAG OUT. START EQUIPMENT. CHECK GROUNDING (WSEA 2-A) CHECK PSI. CSG O PSI. SURFACE 4 PSI. OPEN WELL TO TANK, FLOW CHECK 15 MIN. WELL STATIC (WSEA 10-A) LOAD HOLE W/3 BBLSAND PERFORM BUBBLE/FLOW CHECKAS PER SOP FOR 30 MIN. CSG HAD NO BUBBLES/FLOW, SURFACE HAD BUBBLES/FLOW (WSEA 10-C) RUWL, TAG TOP Of CMT AT 1510, PU 3.5 7.7#JET CUTTER. VERIFY DEPTH W/CCL. JET CUT CSG AT 1505. RDWL CONDITION HOLEW/100 BBLS FRESH WATER. OPEN WELL TO TANK. FLOW CHECK 15 MIN. NO FLOW ND, 7 1/1\$ SK BOP W/2 1/16 PIPE RAMS & BLIND RAMS AND CHANGE' OVER TOOLS TO 3.5.TEST 3.5 PIPE RAMS. 250 PSI FOR 5 MIN. 2000 FOR 15 MIN. TEST CHART IN ATTACHMENTS (WSEA 9-B) • • ND SURFACE HEAD, UN-Lt..ND CSG. NU CROSSOVER SURFACE SPOOL & 7 1/16 SK BOP VI/3.5 PIPE RAMS & BLIND RAMS TOOH LD 34 JTSOF 3.5 7.7#CSG, CHANGE OVER TOOLS T0 2-1/16 TIH W/46JTS AND 110FT SUB OF 21/16 3.25#J-55 IJ TBGAT 1505 RU AXIS GMT CREW. TEST PUMP LINES. PUMP BASE SURFACE PLUG AS FOLLOWS. 5 BBLS FRESH WATER. 35 SACS OR 8.1 BBLS OF 15.2# ETHIXO GMT @1.3 YIELD, DISPLACE 4.2 BBLS. EST CMT 1505-1402 TOOH W/2 1/15 3.25#J-55 IJ TBG. LD 110FT SUB AND 4JTSAND SB 42 JTS SWI.</div>							
Corrective Action:							Date:		

BradenHead			
Date of Last Brhd Test: 05/29/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 1	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:			Date:

Workover	
Comment:	<div>2024/08/19: Plugging Operations: Cementing; Base plug. 2024/08/19: JSA attached as photo to this report. Workover Contractor: JMR Services, LLC Rig #12. Cement Contractor: JMR Services, LLC. Reference: Form 6N on file. Notice of Intent to Abandon date: 06/24/2024. Approved. Form 42 on file. Notice of MIRU. Start Date: 08/16/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 08/16/2024. Approved.</div>
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits:

☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 08/19/2024 at approximately 14:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE65N63W/18NESE Location ID: 330538 Well Name(s): SLW Green State BB 18-09. API: 123-19257. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Base plug. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.396256 / -104.478884 Well GPS coordinates: 40.397159 / -104.473185</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/21/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603117	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673321