

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 1 – South Wellheads



Photo 2 – Production Equipment

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 3 – Heater Treaters



Photo 4 – Production Equipment

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Energy and Carbon Management Commission
40.85949, -103.78424, 4909.2ft
08/14/2024 13:50:25

Photo 5 – Compressor



Energy and Carbon Management Commission
40.86017, -103.78427, 4902.6ft
08/14/2024 13:51:17

Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 7 – Tank Battery



Photo 8 – Tank Battery, Water LACT

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 9 – LACT



Photo 10 – Production Equipment

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 11 – Flare



Photo 12 – Flare and ECD

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 13 – Heater Treaters



Photo 14 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Horsetail 08D PAD
Location ID: 159741



Photo 15 – Signs at Entrance