

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2024

Submitted Date:

08/21/2024

Document Number:

696306663**FIELD INSPECTION FORM**Loc ID 159741 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**ECMC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Parrish, Melissa	970-397-3896	mparrish@fundareresources.com	
Smith, Sydney		ssmith@fundareresources.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159739	WELL	PR	06/01/2021	OW	123-41021	Horsetail 08D-1703	PR
159741	LOCATION	AC			-	Horsetail 08D Pad	AC
159743	WELL	PR	08/19/2015	OW	123-41024	Horsetail 08D-1704	PR
441615	WELL	PR	08/01/2017	OW	123-41445	Horsetail 08D-1734	PR
441616	WELL	PR	08/01/2017	OW	123-41446	Horsetail 08D-1735	PR

**General Comment:**This is a Well PAD and Production Facility Audit

**Location**Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: <a href="#">Automation and Electrical Equipment</a>			
Corrective Action:			Date:
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: LACT	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: <a href="#">Shares berm with the Crude Oil Tanks</a>					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	14	400 BBLs	STEEL AST		40.859890,-103.784400

Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Field Flare		
Comment:	Candlestick Flare does not meet ECMC requirements for Enclosed Combustion.		
Corrective Action:	Comply with Rule 903.(5).	Date:	11/22/2024

Inspected Facilities			
Facility ID: 159739	Type: WELL	API Number: 123-41021	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 159741	Type: LOCATION	API Number: -	Status: AC      Insp. Status: AC
<b>Producing Well</b>			
Comment: PR - Active Production Facility			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 159743	Type: WELL	API Number: 123-41024	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 441615	Type: WELL	API Number: 123-41445	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 441616	Type: WELL	API Number: 123-41446	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
<b>ECMC Comments</b>			
<p>Comment</p> <p>On Wednesday 08/14/2024 at approximately 13:48, I, Inspector Erica Petrie, conducted a Field Audit at Fundare Resources Operating Company LLC, Horsetail 08D PAD, Location #159741 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Audit the following possible Compliance Issues were observed:</p> <p>Candlestick Flare does not meet ECMC requirements for Enclosed Combustion. Comply with Rule 903.(5). Corrective Action date 11.22.2024</p> <p>A follow up on this Site Audit will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules. This is a summary of the Audit Report.</p>	<p>User</p> <p>petrie</p>	<p>Date</p> <p>08/16/2024</p>	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306677	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673396">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673396</a>