

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2024

Submitted Date:

08/21/2024

Document Number:

716200401

FIELD INSPECTION FORMLoc ID 336605 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248953	WELL	SI	06/01/2022	GW	123-16755	HSR-DEBORRAH 7-5	SI
284874	WELL	TA	06/01/2024	GW	123-23898	HUNT 24-5	TA

General Comment:

This is a routine Wellhead audit.

Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type WELLHEAD					
Comment:					
Corrective Action:					
Date:					
Emergency Contact Number:					
Comment:					
Corrective Action:					
Date:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type Area Volume					
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type WELLHEAD					
Comment:					
Corrective Action:					
Date:					
Equipment:					
Type: Plunger Lift # 1					
Comment:					
Corrective Action:					
Date:					
Tanks and Berms:					
Contents # Capacity Type Tank ID SE GPS					
CENTRALIZED BATTERY					
Comment: Battery for 05-13-16755 has been dismantled at location entrance from CR 29. Battery for 05-123-23898 is location number: 487128					
Corrective Action:					
Date:					
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type Capacity Permeability (Wall) Permeability (Base) Maintenance					
Comment:					
Corrective Action:					
Date:					

Inspected FacilitiesFacility ID: 248953 Type: WELL API Number: 123-16755 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 08/25/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284874 Type: WELL API Number: 123-23898 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/03/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 324 Fluid Type: GASEnd Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
This is a routine Wellhead audit. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.	carlilec	08/21/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716200402	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673406