

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

713601353

FIELD INSPECTION FORM

Loc ID 321579 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Steffy Goncalves		SGoncalves@cogc.com	
Citation		ENV-CODNR@cogc.com	
Enforcement		dnr_ecmcenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207340	WELL	PR	08/23/2007	OW	017-06275	MCCORMICK 24-3 6	RI
321579	LOCATION	AC			-	MCCORMICK 24-3-614S49W 3SESW	RI

General Comment:

This is a follow up of the previous inspections; #713600714, #713600871.
The corrective actions of the previous inspections have not been completed.
Non-compliance with the Rules will be referred to enforcement.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			
Crude Oil	WELLHEAD				
Comment: The spill that was initially observed on 2/7/24 has still not been cleaned up. Previous corrective action was not completed.					
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.				Date:	
Lube Oil	Pump Jack				
Comment: The is oil leaking out of the pumpjack engine that must be controlled and cleaned up. There is oil daylighting at the surface which is a hazard to wildlife.					
Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediately Comply with Rule 902 to prevent pollution.				Date:	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601354	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673769