

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2024

Submitted Date:

08/21/2024

Document Number:

715500567

**FIELD INSPECTION FORM**Loc ID 316629 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289438	WELL	SI	10/01/2020	GW	103-10993	ANT HILL UNIT 8-12	SI

**General Comment:****ECMC Inspection Report Summary**

On Wednesday, 08/21/2024, Inspector Kirby Burchett, was on location to witness an Alternate MIT Bradenhead test at KT Resources LLC on the Ant Hill Unit 8-12 well, Location #316629, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Check pressures. Open Bradenhead (Surface casing). Monitor flow and production casing pressure for 30 minutes. Shut in Bradenhead and secure well.

No follow up inspection is required.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment: (800) 288-0560 or 911				
Corrective Action:				
Date:				
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	289438	Type:	WELL	API Number:	103-10993	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		<div>Shut In - 10/1/2020 June 2024 Production Report</div>							
Corrective Action:		<div></div>						Date:	
BradenHead									
Date of Last Brhd Test:		05/23/2024		Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:		<div>August 21, 2024. Alternate MIT Bradenhead test. Shut In Tubing – 925 psi. Shut In Production Casing – 980 psi. Shut In Surface Casing (Bradenhead) – 0 psi Open Bradenhead. No Flow 5 min – No Flow, 10 min - No Flow, 15 min - No Flow, 20 min - No Flow 25 min - No Flow, 30 min – No Flow. Production casing – 980 psi. Shut in Bradenhead. Instantaneous Shut In – 0 psi.</div>							
Corrective Action:		<div></div>						Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12