

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2024

Submitted Date:

08/15/2024

Document Number:

693807645**FIELD INSPECTION FORM**Loc ID 311853 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1141 NORTH LOOP 1604 E 105-414City: SAN ANTONIO State: TX Zip: 78232**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Karcz, Jeffrey	(816) 222-7500	jkarcz@genesigoco.com	
Taylor, Chad		chad.taylor@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293056	WELL	SI	07/01/2023	DSPW	103-11095	FLETCHER GULCH 3-31WD	SI

General Comment:Routine UIC Inspection. Gate locked no access to wellsite.
Issues were found requiring corrective action.

Inspected Facilities

Facility ID: 293056

Type: WELL

API Number: 103-11095

Status: SI

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: SEGO

TC:

Pressure or inches of Hg

Previous Test Pressure

Last MIT: 10/15/2018

Brhd:

Pressure or inches of Hg

Previous Test Pressure

AnnMTReq:

Comment:

Last MIT 10/15/2018.
No current Mechanical Integrity Test (MIT) on record or delinquent as required by Rule 417

Corrective Action:

Perform MIT per Rule 417.a. (1)

Date: 08/30/2024

Method of Injection:

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403890396	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6666400

Date Run: 8/22/2024 Doc [#693807645]

Page 2 of 2