

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403876890

Date Received:

08/05/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name  
Zach Stradling

Phone  
505-325-8874

Email  
zstradling@bmgdrilling.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000836

Inspection Date: 06/12/2024

FIR Submit Date: 06/21/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BENSON-MONTIN-GREER DRILLING CORPORATION

Company Number: 7650

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 325388

Location Name: LA POSTA CANYON-N33N10W Number: 5NENE County: \_\_\_\_\_

Qtrqr: NENE Sec: 5 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137517 Longitude: -107.952021

FACILITY - API Number: 05-067- -00

Facility ID: 325388

Facility Name: LA POSTA CANYON-N33N10W Number: 5NENE

Qtrqr: NENE Sec: 5 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137517 Longitude: -107.952021

CORRECTIVE ACTIONS:

1 CA# 196027

Corrective Action: Regrade/recontour access road per rule 1004a.

Date: 07/31/2024

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator Comment: The access road is at grade with surrounding ground. This area is an active pipeline ROW. HES harrowed, seeded and mulched the access road. Branches and sticks were placed across the road to deter use. The site and access road were showing good growth of native grasses.

ECMC Decision: **Not Approved**

ECMC Representative: Operators response is not sufficient, re-contouring, regrading and compact alleviation has not been performed along the access road. Based on operator comments corrective action does not appear to have been completed. Location will remain out of compliance until the corrective action is addressed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The access road is at grade with surrounding ground. This area is an active pipeline ROW. HES harrowed, seeded and mulched the access road. Branches and sticks were placed across the road to deter use. The site and access road were showing good growth of native grasses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zach Stradling

Signed: \_\_\_\_\_

Title: Vice President

Date: 8/5/2024 1:13:01 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <b><u>Document Number</u></b> | <b><u>Description</u></b> |
|-------------------------------|---------------------------|
| 403876890                     | FIR RESOLUTION SUBMITTED  |
| 403876927                     | Work summary w/ pictures  |

Total Attach: 2 Files