

Interim Reclamation and Stormwater Inspection

Date: 08/19/2024

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 433082

Inspection Document #: 708201528

Morgan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 1. Facing west at the location entrance. Undesirable vegetation (kochia) growing along location and access road.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 2. Northern interim areas are comprised of mainly CO List C Noxious Weed - cheatgrass; it appears that cheatgrass has already seeded out at the time of this inspection.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 3. Eastern interim areas have evidence of non-uniform vegetation cover resulting in bare soil and CO List C Noxious Weed - cheatgrass.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



8/19/24, 12:38 PM
307° NW
ECMC

Photo 4. Some desirable vegetation cover was observed in the southeast corner of the interim areas.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photos 5 & 6. Taken on the topsoil stockpile. The stockpile is predominantly undesirable vegetation (e.g. kochia, russian thistle and CO List C Noxious Weed- cheatgrass).

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 7. Tank/Container within battery does not appear to be properly labeled.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 8. Tank/Container at separator does not appear to be properly labeled.




Photo 9. Tank/Container at flare unit does not have adequate wildlife BMPs to prevent or exclude entry by wildlife. Red arrow indicates wildlife mortality (unidentified bird) within container contents. Oily waste shall be removed and wildlife BMPs installed.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 10. Western interim areas have evidence of non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 11. Stained soil around wellhead.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 12. Wildlife BMPs (netting) inadequate, tank labels are not legible, and oily waste within secondary containment needs to be properly disposed of.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



Photo 13. Hydrocarbon staining at pumpjack motor.

Inspection Photos
Location Name: Wickstrom 18 1H
Location ID: 433082



8/19/24, 12:52 PM
236° SW
ECMC

Photo 14. Maintenance advised along access road to manage stormwater and prevent trackout, and to reduce access road expansion.