

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2024

Submitted Date:

08/16/2024

Document Number:

708302594

**FIELD INSPECTION FORM**

Loc ID 335978	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				<b>Findings:</b> 9 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299283	WELL	PR	05/19/2010	GW	045-17639	N. PARACHUTE EF09C-21 D27A 5	PR
299284	WELL	PR	05/28/2010	GW	045-17640	N. Parachute EF01D-28 D27A 5	PR
299285	WELL	PR	04/21/2010	GW	045-17641	N. PARACHUTE EF12D-22 D27A 5	PR
299286	WELL	PR	03/23/2010	GW	045-17642	N. PARACHUTE EF13B-22 D27A 5	PR
299287	WELL	PR	05/22/2010	GW	045-17643	N. PARACHUTE EF09A-21 D27A 5	PR
299288	WELL	PR	10/27/2008	GW	045-17644	N. PARACHUTE EF11C-22 D27A 5	PR
299289	WELL	PR	03/07/2010	GW	045-17645	N. PARACHUTE EF11A-22 D27A 5	PR
299290	WELL	PR	03/28/2010	GW	045-17646	N. PARACHUTE EF06A-22 D27A 5	PR
299291	WELL	PR	04/19/2010	GW	045-17647	N. PARACHUTE EF05C-22 D27A 5	PR
299292	WELL	PR	04/29/2010	GW	045-17648	N. PARACHUTE EF05A-22 D27A 5	PR
299293	WELL	PR	03/08/2010	GW	045-17649	N. PARACHUTE EF14A-22 D27A 5	PR
299294	WELL	PR	03/21/2010	GW	045-17650	N. PARACHUTE EF06C-22 D27A 5	PR
299295	WELL	PR	05/10/2010	GW	045-17651	N. PARACHUTE EF09D-21 D27A 5	PR
299299	WELL	PR	03/31/2010	GW	045-17652	N. PARACHUTE EF13C-22 D27A 5	PR

299386	WELL	PR	04/18/2010	GW	045-17662	N. PARACHUTE EF12A-22 D27A 5	PR
413296	WELL	PR	03/31/2010	GW	045-18771	N. PARACHUTE EF04A-27 D27A 5	PR

**General Comment:**

CECMC Inspection Report Summary

On 8/14/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW at Location ID #335978 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Open-ended line on gas meter  
2) Wildlife entry hazard on produced water tank

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meter/lift protected by concrete barriers.		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 16		corrective date
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:	Open-ended line on gas meter.		
Corrective Action:	Secure line to comply with Rule 608.e.	Date:	08/21/2024
Type: Ancillary equipment	# 3		

Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Wildlife protective screen on produced water tank does not provide sufficient protection. Screen has been damaged by thief hatch.		
Corrective Action:	Repair/reinstall wildlife protective screen.	Date:	08/21/2024
Type: Bradenhead	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID:	299283	Type:	WELL	API Number: 045-17639 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299284	Type:	WELL	API Number: 045-17640 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299285	Type:	WELL	API Number: 045-17641 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299286	Type:	WELL	API Number: 045-17642 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299287	Type:	WELL	API Number: 045-17643 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299288	Type:	WELL	API Number: 045-17644 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299289	Type:	WELL	API Number: 045-17645 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299290	Type:	WELL	API Number: 045-17646 Status: PR Insp. Status: PR

<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299291	Type:	WELL	API Number: 045-17647 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299292	Type:	WELL	API Number: 045-17648 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299293	Type:	WELL	API Number: 045-17649 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299294	Type:	WELL	API Number: 045-17650 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299295	Type:	WELL	API Number: 045-17651 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299299	Type:	WELL	API Number: 045-17652 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299386	Type:	WELL	API Number: 045-17662 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	413296	Type:	WELL	API Number:	045-18771	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Compaction						
		Ditches				
Berms						
Gravel						
		Culverts				
		Compaction				
		Gravel				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403892605	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668973">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668973</a>
708302595	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668962">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6668962</a>