

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2024

Submitted Date:

08/22/2024

Document Number:

699506209

## FIELD INSPECTION FORM

Loc ID 484179 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Blair, Max	720-862-4503	mblair@gmtexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484722	WELL	PR	12/01/2023	OW	039-06754	Red Lady 6-64 4-6 1HN	PR
484723	WELL	DG	07/15/2024		039-06755	Red Lady 6-64 4-6 2HN	DG
484724	WELL	DG	07/16/2024		039-06756	Red Lady 6-64 4-6 3HN	DG
484725	WELL	DG	07/17/2024		039-06757	Red Lady 6-64 4-6 4HN	DG

**General Comment:**

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 484722 Type: WELL API Number: 039-06754 Status: PR Insp. Status: PR

**Well Drilling**

**Rig:** Rig Name: Ensign Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** At time of inspection drilling rig had TD well @ 20,630' MD and began to TOH with drill pipe.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484723 Type: WELL API Number: 039-06755 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484724 Type: WELL API Number: 039-06756 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484725 Type: WELL API Number: 039-06757 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>At time of inspection location appears to be in compliance with ECMC rules.</u> <u>At time of inspection weather conditions were Hot, clear, light wind.</u>	medinaj	08/22/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506210	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679167">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679167</a>