

# Inspection Photos

API: 055-06278

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the access road. There is sediment being deposited on the road from the ditch along the road side further up the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Drone aerial photo facing down toward the ditch along the access road. The check dams have fallen apart and the ditch is not stabilized.





## Inspection Photos



**Photo 3.** Drone aerial photo facing southwest along the access road. The area at the red arrow appears to have erosion issues.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Drone aerial photo facing northeast toward the location. There is a perimeter run-on ditch along the northwest side of the pad that appears to be causing erosion.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:055-06278 | Date: 8/22/2024



## Inspection Photos



**Photo 5.** Drone aerial photo facing southeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources