

Inspection Photos

API: 055-06190

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 6. Drone aerial photo facing northwest toward the location.



Inspection Photos



Photo 2. Facing northwest. The cut slope is not stabilized and has signs of erosion.



Inspection Photos



Photo 3. Facing west toward the location. The road continues on past the location.



Inspection Photos



Photo 4. Facing southeast at the location.



Inspection Photos



Photo 5. Facing southwest at the location.



Inspection Photos



Photo 6. South side of the location facing east along the fill slope.



Inspection Photos



Photo 7. There is field bindweed throughout the location that will need to be controlled. There is a capped flowline riser that needs to be removed or cut 3' below the surface.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources