

**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



Energy and Carbon Management Commission  
40.58344; -103.73595, 4613.6ft  
08/20/2024 13:46:14

**Photo 1 – Tank Battery**



Energy and Carbon Management Commission  
40.58348; -103.73591, 4612.5ft  
08/20/2024 13:46:25

**Photo 2 – Tank Battery Sign**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 3 – Tank Berm**



**Photo 4 – Tank Berm**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 5 – Tank Berm**



**Photo 6 – Stained Soil at Southeast Tank Loadline Valve**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 7 – Tank Battery – North Tanks – Berms**



**Photo 8 – Tank Berm**





**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 9 – Skim Tank**



**Photo 10 – Pit Area – Looking East**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 11 – Pit Area – Looking West**



**Photo 12 – Wellhead**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 13 – Wellhead – Stained Soil**



**Photo 14 – Pumping Unit**

**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 15 – Heater Treater**



**Photo 16 – Unmarked Riser**



**Inspection Photos**  
**Location Name: Henderson 1**  
**Location ID: 331730**



**Photo 17 – Heater Treater Berms**



**Photo 18 – Unmarked Risers at Tanks**