

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2024

Submitted Date:

08/23/2024

Document Number:

696306679

**FIELD INSPECTION FORM**Loc ID 331730 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 83555

Name of Operator: SUNBURST INC

Address: P.O. BOX 140266

City: EDGEWATER State: CO Zip: 80214

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carnes, Greg		gcarnes@kc.rr.com	
Jackson, Jay		sun1045@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265438	WELL	SI	10/01/2023	OW	123-21201	HENDERSON 1	SI

**General Comment:**

This is a Well and Tank Battery Audit

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers East of Heater Treater, and at Tank Valves. See Photos - Disconnected flowline risers not OOSLAT; see photos		
Corrective Action:	Comply with Rule 1105	Date:	09/06/2024
Type	OTHER		
Comment:	Stained Soil at Wellhead and Southeast Crude Oil Tank Loadline Valve.; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Conduct maintenance on equipment, cleanup stained material. Per Rule 1002..(2).D and review self inspection processes.	Date:	09/06/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		

Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Berm around Heater Treater is compromised; see photos		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.		Date: 09/27/2024
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	STEEL AST		40.583440,-103.735810
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms are compromised, see photos			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 09/27/2024

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 265438

Type: WELL

API Number: 123-21201

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>On Tuesday 07/23/2024 at approximately 13:42, I, Inspector Erica Petrie, conducted a Field Audit at Sunburst INC, Henderson 1, Location #331730 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Audit the following possible Compliance Issues were observed:</p> <p>Stained Soil at Wellhead and Southeast Crude Oil Tank Loadline Valve. Comply with Rule 905.e. and Comply Rule 1002..(2).D. Corrective Action Date 09.06.2024</p> <p>Unmarked Risers at Tanks and East of Heater Treater. Comply with Rule 1105. Corrective Action Date 09.06.2024</p> <p>Tank Berms are compromised. Comply with Rule 603.o. Corrective Action Date 09.27.2024</p> <p>Berm around Heater Treater is compromised. Comply with Rule 603.o. Corrective Action Date 09.27.2024</p> <p>A follow up on this Site Audit will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules. This is a summary of the Audit Report.</p>	petrie	08/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306680	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679834">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679834</a>