

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Entrance to location - Photo #04840



Location - Photo #04856

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Wellheads - Photo #04841



Separators - Photo #04843

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Separators - Photo #04845



Glycol heater/pump - Photo #04848

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Tank battery - Photo #04857



NW corner of location - Photo #04874

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



NE corner of location - Photo #04875



SE corner of location - Photo #04876

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



SW corner of location - Photo #04878



Doors open/Wildlife hazard - Photo #04852

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Doors open/Wildlife hazard - Photo #04854



Wildlife hazard - Photo #04855

Inspection Photos

Location: CHEVRON USA INC SKR-66S98W/9SENE

Location ID: 336050

Date: 8/21/2024



Open ended load line - Photo #04859



Label is weathered and peeling - Photo #04871

