

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2024

Submitted Date:

08/23/2024

Document Number:

713400267

FIELD INSPECTION FORM

Loc ID 336050	Inspector Name: Popejoy, Dusty	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: ECMC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 760 HORIZON DRIVE STE 401 City: GRAND JUNCTION State: CO Zip: 81506				Findings: 40 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CHEVRON		atlx@chevron.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295965	WELL	PR	08/02/2012	GW	045-15865	SKR 698-09-AV-04	PR
298601	WELL	PR	07/19/2012	GW	045-17281	SKR 698-09-AV-03	PR
298602	WELL	PR	07/01/2013	GW	045-17282	SKR 698-09-AV-22	PR
298603	WELL	PR	09/01/2012	GW	045-17283	SKR 698-09-AV-21	PR
298604	WELL	PR	04/01/2022	GW	045-17284	SKR 698-09-AV-20	PR
298605	WELL	PR	08/31/2012	GW	045-17285	SKR 698-09-AV-19	PR
298606	WELL	PR	11/01/2023	GW	045-17286	SKR 698-09-AV-18	PR
298607	WELL	PR	07/01/2013	GW	045-17287	SKR 698-09-AV-16	PR
298608	WELL	PR	08/25/2012	GW	045-17288	SKR 698-09-AV-15	PR
298610	WELL	PR	08/08/2012	GW	045-17289	SKR 698-09-AV-14	PR
298611	WELL	PR	08/23/2012	GW	045-17290	SKR 698-09-AV-13	PR
298612	WELL	PR	12/13/2011	GW	045-17291	SKR 698-09-AV-12	PR
298613	WELL	PR	12/10/2011	GW	045-17292	SKR 698-09-AV-11	PR
298614	WELL	PR	12/20/2011	GW	045-17293	SKR 698-09-AV-10	PR
298615	WELL	PR	12/24/2011	GW	045-17294	SKR 698-09-AV-09	PR
298616	WELL	PR	07/01/2013	GW	045-17295	SKR 698-09-AV-08	PR
298617	WELL	PR	12/07/2011	GW	045-17296	SKR 698-09-AV-07	PR
298618	WELL	PR	07/17/2012	GW	045-17297	SKR 698-09-AV-01	PR
298619	WELL	PR	07/31/2012	GW	045-17298	SKR 698-09-AV-02	PR
298620	WELL	PR	07/22/2012	GW	045-17299	SKR 698-09-AV-05	PR
298621	WELL	PR	08/29/2012	GW	045-17300	SKR 698-09-AV-17	PR

298622	WELL	PR	04/14/2012	GW	045-17301	SKR 698-09-AV-06	PR
412116	WELL	PR	08/01/2013	GW	045-18438	SKR 698-09-AV-24	PR
412117	WELL	PR	07/14/2012	GW	045-18439	SKR 698-09-AV-23	PR

General Comment:

CECMC Inspection Report Summary

On 8/21/2024 at approximately 12:04, Compliance Inspector Dusty Popejoy conducted an on-site inspection at CHEVRON USA INC SKR-66S98W/9SENE at Location ID #336050 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Equipment:

- 1- Multiple separator doors opened to wildlife/ available for entry by wildlife with a CA date of 8/30/2024
- 2- Separator burner open to wildlife/ available for entry by wildlife with a CA date of 8/30/2024
- 3- Open ended load line on tank with a CA date of 9/2/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location**Lease Road:**

Type	Access		
comment:	Access.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks. 1 label is peeling off and needs replaced.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/1-877-257-6007	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Glycol pump.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Separator burner open to wildlife/ available for entry by wildlife, refer to photos.		Date:	
Corrective Action:	Comply with CECMC wildlife rules.		Date:	08/30/2024
Type: Bradenhead	# 20			
Comment:	All Bradenhead valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 4			
Comment:	All Bradenhead valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 20			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Control building.		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Open ended load line on tank, refer to photos.		Date:	
Corrective Action:	All load lines will be capped or plugged.		Date:	09/02/2024
Type: Horizontal Heated Separator	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Charge pump.		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 5			
Comment:	Chemical tanks.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 13			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Multiple separator doors opened to wildlife/ available for entry by wildlife, refer to photos.		Date:	
Corrective Action:	Comply with CECMC wildlife rules.		Date:	08/30/2024
Type: Other	# 1			
Comment:	Glycol heater.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 20			
Comment:				

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		,	
Comment: Telemetry on tank.						
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID:	295965	Type:	WELL	API Number: 045-15865 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298601	Type:	WELL	API Number: 045-17281 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298602	Type:	WELL	API Number: 045-17282 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298603	Type:	WELL	API Number: 045-17283 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298604	Type:	WELL	API Number: 045-17284 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298605	Type:	WELL	API Number: 045-17285 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298606	Type:	WELL	API Number: 045-17286 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID:	298607	Type:	WELL	API Number: 045-17287 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well.			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				

<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298608	Type:	WELL	API Number: 045-17288 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298610	Type:	WELL	API Number: 045-17289 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298611	Type:	WELL	API Number: 045-17290 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298612	Type:	WELL	API Number: 045-17291 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298613	Type:	WELL	API Number: 045-17292 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298614	Type:	WELL	API Number: 045-17293 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298615	Type:	WELL	API Number: 045-17294 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well.			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298616	Type:	WELL	API Number:	045-17295	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298617	Type:	WELL	API Number:	045-17296	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298618	Type:	WELL	API Number:	045-17297	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298619	Type:	WELL	API Number:	045-17298	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298620	Type:	WELL	API Number:	045-17299	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298621	Type:	WELL	API Number:	045-17300	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	298622	Type:	WELL	API Number:	045-17301	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing well.							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	412116	Type:	WELL	API Number:	045-18438	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	412117	Type:	WELL	API Number:	045-18439	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Other				Material Handling And Spill Prevention		Chemical tank containments
Ditches						
		Gravel				
Seeding						
		Culverts				
Gravel						
Berms						
		Compaction				
Compaction						
		Ditches				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400268	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6680027