

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 5851 From entrance to location




Photo # 5852 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 5853 Location



Photo # 5854 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 5855 Location



Photo # 5856 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 5857 Hole in liner/liner needs maintenance



Photo # 5858 Hole in liner/liner needs maintenance



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5859 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5860 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5861 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5862 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5863 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5864 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5865 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5866 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5867 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5868 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5869 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5870 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5871 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5872 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



**Photo # 5873 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5874 Barbed wire fence needs maintenance/wildlife hazard**