



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/26/2024
Submitted Date:
08/26/2024
Document Number:
717700230

Loc ID
434585

Inspector Name:
Burns, Adam

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:
ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
Findings:
12 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c	All Inspections
,		hevron.onmicrosoft.com	
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434586	WELL	SI	01/01/2023	OW	123-38270	Guttersen 31Q-221	SI
434589	WELL	SI	12/01/2023	OW	123-38273	Guttersen 6M-303	SI
434734	WELL	SI	01/01/2023	OW	123-38302	Guttersen 31T-301	SI
434735	WELL	SI	01/01/2023	OW	123-38303	Guttersen 31T-441	SI
434736	WELL	SI	01/01/2023	OW	123-38304	Guttersen 31Q-401	SI
436520	WELL	SI	02/01/2024	OW	123-39169	Guttersen 6R-403	SI

General Comment:

This is an audit on the wells that are SI.

Date Run: 8/26/2024 Doc [#717700230]

Page 1 of 6

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	NG engine		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 434586 Type: WELL API Number: 123-38270 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI
LO/TO
MIT to be done on 9-11-24 document #403898067
Form 05B-00 on file document #403752916

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/30/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434589 Type: WELL API Number: 123-38273 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI "LO/TO"

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/30/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434734 Type: WELL API Number: 123-38302 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI "LO/TO"
MIT to be completed on 9/9/24. Document #403898058
Form 05B-00 on file Document #403752913

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434735 Type: WELL API Number: 123-38303 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:Comment: SI "LO/TO"
Form 05B-00 on file. Document #403752897
Last production recorded was 12/1/2022

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434736 Type: WELL API Number: 123-38304 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:Comment: SI "LO/TO"
Form 05B-00 on file. Document #403752890
Last production date was 12/2022

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436520 Type: WELL API Number: 123-39169 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:Comment: SI "LO/TO"
Last production recorded was 1/2024

Corrective Action:

Date:

BradenHead		
Date of Last Brhd Test:	<u>04/30/2024</u>	Annual Brhd Completed? <u>Yes</u>
Last Brhd Test Results	Initial Surf Csg Pressure: <u>0</u>	Fluid Type: _____
	End Surf Csg Pressure: <u>0</u>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700231	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681565