

## Inspection Photos


Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



Location - Photo #04908



Wellheads - Photo #04882



## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



Aug 21, 2024 at 2:41:38 PM  
+39.578071,-108.340997 ±4.70m



Aug 21, 2024 at 2:42:09 PM  
+39.577968,-108.341034 ±4.71m

Separators - Photo #04898

Separators - Photo #04899



## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



Glycol heater/pump - Photo #04904



Tank battery - Photo #04907



## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



Control building - Photo #04914



Air compressor building - Photo #04915



## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



NE corner of location - Photo #04919



NW corner of location - Photo #04920



## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



SW corner of location - Photo #04921



No tank labeling - Photo #04891

## Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW

Location ID: 336054

Date: 8/21/2024



No tank labeling - Photo #04892



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources