

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2024

Submitted Date:

08/26/2024

Document Number:

707603130**FIELD INSPECTION FORM**Loc ID 305974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284168	WELL	TA	05/24/2017	GW	123-23763	MCKENNEY 14-12	PA

**General Comment:**This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Plugging Operations: Cementing; Initial plug(s).

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.493233 / -104.516536

Well GPS coordinates: 40.492200 / -104.515640

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 284168 Type: WELL API Number: 123-23763 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: Ranger Well Svcs.

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 6590'

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

2024/08/23:

Plugging Operations: Cementing; Initial plug(s).

2024/08/23: JSA attached as photo to this report.

Workover Contractor: Ranger Well Services, Rig #BW-1543.

Cement Contractor: Ranger Well Services.

JSA SAFETY MEETING. CHECK PRESSURE- TBG O PSI / CSG O PSI /

SURF CSG O PSI.

TOOH LO 100 MORE JNTS + SN &amp; RET HEAD ( 188 JMTS 2-3/8' TBG PULLED FROM

WELL IN

TOTAL ).

JSA SAFETY MEETING, MIRU RES WIRELINE. RIH WITH GR/JB+ CCL AND TAG RBP

SAND CAP

AT 6597 RIH W/ 10K CIBP FOR 4-1/2" CSG TIO ONTO CSL CSG COLLARSAND SET

PLUG @

6590', DUMP BAIL 2 SKS CMT= TOC 6564'. PRESSURE TEST CSG TO 1517 PSI FOR

15

MINUTES ( WSE.A 10-B ). ENDING PRESSURE 1505 PSI. TEST SUCCESSFUL W/ 12

PSI

DECLINE. WL RIH W/ JET CUTTER AND CUT PROD CSG @2389'. POOH AND RDMO

WL.

ESTABLISH FORWARD CIRCULATION AND CONDITION THE HOLE CLEAN W/ 280

BBL ( 2 x

BU }, RETURNS CLEANED UP AFTER FIRST BU. LET THE WELL RELAX. RIG DOWN

WORK

FLOOR AND SECURE THE WELL / LOTO. DEBRIEF. SDFN.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/22/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**

Comment: 2024/08/23:  
Plugging Operations: Cementing; Initial plug(s).  
2024/08/23: JSA attached as photo to this report.

Workover Contractor: Ranger Well Services, Rig #BW-1543.  
Cement Contractor: Ranger Well Services.

Reference:  
Form 6N on file. Notice of Intent to Abandon date: 08/05/2024. Approved.  
Form 42 on file. Notice of MIRU. Start Date: 08/16/2024. Approved.  
Form 42 on file. Notice of Plugging Operations. Start Date: 08/116/2024. Approved.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 08/23/2024 at approximately 12:39 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: MCKENNEY-66N64W/14NWNE Location ID: 305974 Well Name(s): McKenney14-12. API: 123-23763. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Plugging Operations: Cementing; Initial plug(s). Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.401320 / -104.487810 Well GPS coordinates: 40.401450 / -104.486840 Portable gas monitors installed at jobsite.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603131	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681961">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681961</a>
707603132	2024-08-23; JSA	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681962">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681962</a>