

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2024

Submitted Date:

08/26/2024

Document Number:

708904426

FIELD INSPECTION FORM

Loc ID: 324285
Inspector Name: Smelser, Wayne
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 20 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273767	WELL	PR	01/27/2005	GW	045-10275	CLOUGH RWF 14-13	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 08/26/2024 at approximately 09:14 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 14-13 Pad. Location # 324285 in Garfield County Colorado.
 Location is within High Priority/Density Habitat areas & in close proximity to Bald Eagle Roost site. Location is approximately 24 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Stormwater - Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment with a CA date of 09/10/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	Well on plunger lift	
Corrective Action:		Date:
Type: Deadman # & Marked	# 5	
Comment:	Marked	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 273767 Type: WELL API Number: 045-10275 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Erosion & transport of sediment off location
Gravel						Sparse to none in some areas
		Culverts				
		Compaction				
Ditches						
		Ditches				
Rip Rap						
		Gravel				Sparse to none in most sections
Compaction						Light compaction in some areas

Comment: 1. Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 09/10/2024

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Stormwater for corrective action	smelserw	08/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904427	Inspection 708904426 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6682556
708904428	Inspection 708904426 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6682557