



Operator: 8 North

Location Name: GALLEGOS PC GJ 13-99HZ

Loc ID: 417344

Inspection: 684905115









CA: Stained soil at wellhead. Comply with rule 603.f.

CA Resolution: Operator has provided photo evidence showing that the stained soil has been addressed, and the location is currently in compliance with the 900 and 600 series.

CA: Unused equipment around pump jack

CA Resolution: Unused equipment has been removed from the location to comply with the 600 series.

CA: Debris in treater house. Comply with rule 603.f.

CA Resolution: Operator has addressed identified debris and it has been removed from the location to comply with the 600 series.

CA: Gas engine; stained soil at engine. Properly treat or dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil has been addressed, and the location is currently in compliance with the 900 and 600 series.