

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2024

Submitted Date:

08/27/2024

Document Number:

715800140

**FIELD INSPECTION FORM**

Loc ID: 333238 Inspector Name: Revas, Robbie On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240748	WELL	SI	02/01/2024	GW	123-08536	JILLSON 2	SI

**General Comment:**

[This is a Wellsite & tank battery Audit/Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	rutted an needs some work		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate they are fading and will need to be updated in the near future		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Faded and need to be replaced Install sign to comply with Rule 605.g.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Adequate		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type			
Comment:	Wellsite rutted and needs some work		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	fabricated steel pipe and round stock		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Gas Meter Run	# 1		
Comment:	Card indicates current calibration		
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment:	electric motor		Date:	
Corrective Action:			Date:	
Type:	Horizontal Heated Separator	# 1		
Comment:			Date:	
Corrective Action:			Date:	
Type:	Ancillary equipment	# 3		
Comment:	Automation, Electric panel meter box and transformers		Date:	
Corrective Action:			Date:	
Type:	Emission Control Device	# 1		
Comment:			Date:	
Corrective Action:			Date:	
Type:	Bird Protectors	# 2		
Comment:			Date:	
Corrective Action:			Date:	
Type:	Bradenhead	# 1		
Comment:	SI		Date:	
Corrective Action:			Date:	
Type:	Pump Jack	# 1		
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:	no indication of contents(label placards), Install sign to comply with Rule 605.h.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					
Date:					

<b>Paint</b>	
Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Share containment with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.116640,-105.991100
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**


API Number
123-09191
123-08536
123-09192
123-08574
123-08510
123-09550

**AirsID**

API Number	AirsID
------------	--------

<b>Venting:</b>	Yes/No	NO		
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:



**Inspected Facilities**

Facility ID: 240748 Type: WELL API Number: 123-08536 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Audit/Inspection</a> Any corrective actions from previous Inspections that have not been addressed are still applicable Weather: Clear Temperature: 83* Location: Dry.	revasr	08/27/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800141	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684132">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684132</a>