

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2024

Submitted Date:

08/25/2024

Document Number:

695110172**FIELD INSPECTION FORM**Loc ID 322114 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10754Name of Operator: FOUR CORNERS ENERGY LLCAddress: 500 DALLAS STREET #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rhankins@americanhelium.us	
,		JFulcher@bwenergyllaw.com	
Demarco, Jaime		jdemarco@blm.gov	
		rhankins@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209003	WELL	PR	03/01/2024	GW	033-06108	BREWER FEDERAL 2-17	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	PHOTO 5: VEHICLE TRACKING AND STORM WATER HAVE ERODED ROW AND IS CAUSING VEHICLE TO SIDETRACK AND MAKE ROAD WIDER.		
Corrective Action:	REPAIR ROW AND INSTALL BMP'S TO PREVENT VEHICLE TRACKING AND STORMWATER EROSION PER RULE 1002.	Date:	09/06/2024

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.	Date:	10/26/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		37.643334,-104.961702	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	400 BBL				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		37.643346,-104.961776	
Comment:						
Corrective Action:						

Paint

Condition					
Other (Content)					
Other (Capacity)	400 BBL				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	209003	Type:	WELL	API Number:	033-06108	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:					Date:				
BradenHead									
Date of Last Brhd Test:		12/12/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Fail			

Comment: SEE LEASE ROAD SECTION FOR CORRECTIVE ACTION

Corrective Action: Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
THE CA TO POST SIGN WAS ADDRESSED HOWEVER EMERGENCY CONTACT INFORMATION IS NOT ACCURATE AEE SIGN SECTION FOR CORRECTIVE ACTION.	beardslt	08/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110186	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684492