

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2024

Submitted Date:

08/20/2024

Document Number:

713301070

**FIELD INSPECTION FORM**Loc ID 305330 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
McGee, Kerr	970-515-1500	ECMCInspections@Oxy.com	all inspection

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276677	WELL	SI	07/01/2021	OW	123-22808	SWINK 43-21	SI

**General Comment:**

facility inspection

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation around all production equipment		
Corrective Action:	Comply with Rule 606, overgrown vegetation	Date:	08/27/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	metal panels, Form 6A on file 7-22-2022 well head disconnected with fittings plugged		
Corrective Action:		Date:	

**Equipment:**

corrective date

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	electric/automation panels		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	western/midstream		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 Bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shared with Crude tank				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 276677 Type: WELL API Number: 123-22808 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITIONComment: Form 6A on file 7-22-2022 well head disconnected with fittings pluggedCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 02/20/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site inspection, audit of scout card and related documents</u> <u>Location: Swink 43-21</u> <u>Operator: Kerr McGee</u> <u>API#: 123-22808</u> <u>County: Weld</u> <u>While there, I observed production site</u> <u>During this inspection the following possible compliance issues were observed:</u>  <u>Overgrown vegetation, Rule 606, corrective action date 8-27-24, photos 1,2,3 &amp; 4</u>  <u>Weather conditions: sunnyt and dry</u> <u>A follow up on this site inspection needs to be conducted to ensure the</u> <u>Compliance issues have been corrected to comply with ECMC rules.</u>  <u>This inspection does not nullify any orders or NOAV from the ECMC.</u> <u>This is a continuing education inspection.</u>	<u>kesterm</u>	<u>08/20/2024</u>

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>403895698</u>	<u>INSPECTION SUBMITTED</u>	<u><a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672734">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672734</a></u>
<u>713301071</u>	<u>site pic</u>	<u><a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672733">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6672733</a></u>