

# Inspection Photos

August 23rd, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326204

Inspection Document #: 714001133

La Plata County, CO

Township: SWSE 14 35N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos

Location Name: Huber SPC Federal 2-14

Location ID: 326204



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the project area taken from the southern edge facing center. Note: Infestation of noxious weeds dominating the project area. Noxious weeds include Mullein and Musk thistle.

API #: 067-07645



Inspection Photos

Location Name: Huber SPC Federal 2-14

Location ID: 326204



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the western cut slope. Vegetation is progressing in this area with perennial grasses and Penstemon observed establishing on the cut slope.

API #: 067-07645



Inspection Photos

Location Name: Huber SPC Federal 2-14

Location ID: 326204



8/23/24

+37.297806,-107.710005

56° NE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Reference area comprised of Gambel oak, Pine and Smooth brome.

API #: 067-07645