

Operator: 8 North

Location Name: MARICK 1061-6-41

Loc ID: 410175

Inspection: 684904645



CA: Stained soil at wellhead. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed to comply with the 600 and 900 series.