

**Operator: 8 North**

**Location Name: RASMUSSEN-611N61W 29SWSW**

**Loc ID: 302796**

**Inspection: 691400032**







**CA:** Wellhead sign is for prior operator. Install sign to comply with Rule 210.e.

**CA Resolution:** Wellhead sign displays the current operator and provides contact number in the event of an emergency.

**CA:** UNUSED EQUIPMENT -Flywheel guard is off, unknown object on pumpjack base leaking fluid to the ground. Comply with Rule 603.f .

**CA Resolution:** Unused equipment was removed from the location to comply with the 600 series.

**CA:** DEBRIS-Miscellaneous debris in motor room. Comply with Rule 603.f .

**CA Resolution:** Identified debris has been addressed and removed to comply with the 600 series.

**CA:** Stained soil around wellhead and at the north side of motor room. Comply with Rule 603.f .

**CA Resolution:** Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed to comply with the 600 and 900 series.