

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2024

Submitted Date:

08/29/2024

Document Number:

717700270

FIELD INSPECTION FORM

Loc ID: 446992 Inspector Name: Burns, Adam On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|----------------------------------|---------------------------------|
| , | | Inspections@civiresources.com | All Inspections |
| , | | dnr_cogccengineering@state.co.us | |
| Gomez, Jason | | jason.gomez@state.co.us | |
| Leonard, Mike | | mike.leonard@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------------|-------------|
| 446990 | WELL | PA | 06/27/2019 | OW | 123-43430 | Anschutz Equus Farms 3-62-4-2417C2 | TA |

General Comment:

[This is an audit on the well and documents on file](#)

Location

Overall Good:

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well name wrote on well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 446990 Type: WELL API Number: 123-43430 Status: PA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is T/A
 Form 42 on file. Document #401709694
 Form 6(S) on file. Document #402119115. Plug date shows 7/26/2018.

 Well file documentation shows that the well was P/A in 2018 but appears to be T/A. To maintain compliance verify there is no gas leak on the well and the integrity of the well plugs. Once verified Cut and Cap Well.

Corrective Action: **Comply with Rule 434** Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Tuesday, August 27, 2024, at approximately 8:45 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Well: Anschutz Equus Farms 3-62-4-2417C2 Operator: Civitas API: 05-123-43430 County: Weld Well is T/A Form 42 on file. Document #401709694 Form 6(S) on file. Document #402119115. Plug date shows 7/26/2018. During the inspection, a shut in well was observed. The following possible compliance issues were identified: Incorrect Well Name: Well name wrote on well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. Install sign to comply with Rule 605.d. Well Abandonment: Well file documentation shows that the well was P/A in 2018 but appears to be T/A. To maintain compliance verify there is no gas leak on the well and the integrity of the well plugs. Once verified Cut and Cap Well. Comply with Rule 434 A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p> | burnsa | 08/29/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 717700271 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686715 |