

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2024

Submitted Date:

08/29/2024

Document Number:

699700392

FIELD INSPECTION FORM

Loc ID 316060 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Puechner, Rachel	(970) 5605998	RPuechner@chevron.com	Wilson Creek Contact

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232022	WELL	PA	10/06/2022	OW	103-09693	WILSON CREEK UNIT 69	EI
482454	SPILL OR RELEASE	CL	10/28/2022		-	SPILL/RELEASE POINT	EI
482864	SPILL OR RELEASE	CL	09/09/2022		-	SPILL/RELEASE POINT	EI
483282	SPILL OR RELEASE	CL	11/17/2022		-	WILSON CREEK UNIT 69	EI

General Comment:

[ECMC Environmental Inspection. Well is P&A, location appears to be recontoured.](#)

Inspected Facilities

Facility ID: 232022 Type: WELL API Number: 103-09693 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 482454 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 482864 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 483282 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700393	20240821 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686703