

Operator: CPR

Location Name: Prosper Farms 4-65 2-1-6

Loc ID: 443722

Inspection: 713900897



Site mowed berm repaired

Prosper Farms 4-65 2-1-6
28 Aug 2024, 08:55:50



CA: Weed debris in the form of tumbleweeds, new germination and full stature plants were observed throughout interim areas within the permanent location fence as well as outside along topsoil stockpiles. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. See inspection photos for details. Comply with Rule 606 to remove weed debris.

CA Resolution: Operator has reported that the location has been appropriately mowed and weeds have been mitigated to comply with the 600 series.



CA: Unused debris such as t-posts and loose pipe were observed around the porta john area at the entrance to the well location. See inspection photos for details. Comply with Rule 606 to remove debris.

CA Resolution: Operator has reported that the identified unused equipment on location has been removed to comply with the 600 series.

CA: Loose wires were observed daylighting at the Southwest corner of the production facility. See inspection photos for details. Comply with Rule 606 to remove debris.

CA Resolution: Operator has reported that the identified unused equipment on location has been removed to comply with the 600 series.