

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2024

Submitted Date:

08/29/2024

Document Number:

698602240

**FIELD INSPECTION FORM**

Loc ID: 304087    Inspector Name: St John, William (Cal)    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE    State: CO    Zip: 80424

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254045	WELL	PR	01/01/2019	GW	125-07923	STULP 41-1	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Well sign located at wellhead.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Well sign posted at Access Road intersection.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No well lease sign at remote metering location. Well information verified using Meter Calibration/Test Log.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 09/30/2024
Emergency Contact Number:			
Comment:	Emergency contact information posted on well sign.		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Post and Wire fencing around surface equipment at remote gas metering location.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at wellhead.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Dehydrator	# 1		corrective date
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located N off access trail towards State 1-36-247. Digital Gas Meter Run. Meter Calibration/Test Log dated 8-12-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:			Date:
Type: Vertical Separator	# 0		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.088580,-102.570980
Comment:	Located at well location.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	No berms.				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 254045 Type: WELL API Number: 125-07923 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.](#)  
[Electronic Well File reflects last Production/Status reported 6/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602312	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6687391">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6687391</a>