

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2024

Submitted Date:

08/23/2024

Document Number:

708302627

**FIELD INSPECTION FORM**

Loc ID 334626	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258716	WELL	PR	12/12/2000	GW	045-07650	KNIGHT PA 41-5	PR
280663	WELL	PR	10/17/2005	GW	045-11315	KNIGHT PA 512-4	PR
280716	WELL	PR	07/20/2006	GW	045-11325	KNIGHT PA 441-5	PR
280717	WELL	PR	10/18/2005	GW	045-11326	KNIGHT PA 641-5	PR
280719	WELL	PR	07/20/2006	GW	045-11327	KNIGHT PA 511-4	PR
280720	WELL	PR	07/20/2006	GW	045-11328	KNIGHT PA 12-4	PR
280721	WELL	PR	03/08/2007	GW	045-11329	KNIGHT PA 312-4	PR
280722	WELL	PR	07/20/2006	GW	045-11330	KNIGHT PA 341-5	PR
280723	WELL	PR	07/20/2006	GW	045-11331	KNIGHT PA 411-4	PR
280724	WELL	PR	07/20/2006	GW	045-11332	KNIGHT PA 412-4	PR
280725	WELL	PR	10/18/2005	GW	045-11333	KNIGHT PA 541-5	PR

**General Comment:****CECMC Inspection Report Summary**

On 8/20/2024 at approximately 10:45, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/5NENE at Location ID #334626 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Unused equipment stored on location

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment stored on location.		
Corrective Action:	Remove unused equipment to comply with Rule 606.	Date:	08/15/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Bradenhead	# 11				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	CataFlow				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 10				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Liquid nitrogen tank				
Corrective Action:				Date:	
Type: Pig Station	# 11				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 6				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 10				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						

Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID:	258716	Type:	WELL	API Number: 045-07650 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280663	Type:	WELL	API Number: 045-11315 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280716	Type:	WELL	API Number: 045-11325 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280717	Type:	WELL	API Number: 045-11326 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280719	Type:	WELL	API Number: 045-11327 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280720	Type:	WELL	API Number: 045-11328 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280721	Type:	WELL	API Number: 045-11329 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	280722	Type:	WELL	API Number: 045-11330 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280723	Type:	WELL	API Number:	045-11331	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280724	Type:	WELL	API Number:	045-11332	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280725	Type:	WELL	API Number:	045-11333	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
		Gravel				
Gravel						
Compaction						
		Ditches				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403899496	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679878">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679878</a>
708302628	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679877">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6679877</a>