

CORRECTIVE ACTION REPSONSE

DOCUMENT NUMBER: 696205961
FACILITY ID: 210835
API # 045-06593
FACILITY NAME: CHEVRON SHALE 1-25A

COMMENT FROM THE INSPECTION REPORT DATED 9 JULY 2024:

Inspection required Operator to comply with 1004 Rules.

It was observed in this inspection that the Location remains out of compliance with ECMC Rules and Corrective actions: Location and access road have not been recontoured/regraded reclaimed in accordance with Rule 1004.a. Cut and fill slopes remain apparent. Additionally, topsoil remains bare and stockpiled on the north, west and southeastern ends of the location, and has not been replaced.

RESPONSE TO THE ABOVE RULE 1004.a COMMENT:

Reclamation of the CHEVRON SHALE 1-25A in accordance with Rule 1004.a will commence in the 2025 season. The pad will be recontoured to match pre-existing contours and topsoil will be redistributed after the pad is recontoured. After 1-25A is recontoured the pad will be seeded with the appropriate seed mix with soil supplements added to encourage quick plant growth.

At the same time the well pad is reclaimed the road to the pad will be reclaimed, recontoured, and seeded with additional soil supplements.

The following is the proposed footprint of the reclaimed area:



REPSONSE TO THE FOLLOWING COMMENT:

Undesirable Plant Species (Mullein) have continued to establish and spread on the location and access road.

Rushing Vegetations Management was escorted to the 1-25A well on 7 August 2024 pad and all noxious weeds were sprayed with herbicide to rid the pad area of all noxious weeds. Mullen was evident as the above comment indicates and was sprayed with herbicide as noted in the following pictures.





**HERBICIDE APPLIED
TO NOXIOUS WEEDS**



**HERBICIDE BEING APPLIED TO
NOXIOUS WEEDS ON
CHEVRON 1-25A**