

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2024

Submitted Date:

08/29/2024

Document Number:

714201584

**FIELD INSPECTION FORM**

Loc ID 476282 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476282	LOCATION	AC			-	Musick-McClintock 3, 5	AC

**General Comment:**

[This is an audit of MUSICK-MCCLINTOCK TANK BATTERY scout card and related documents followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	sign is damaged. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	09/12/2024
Type	TANK LABELS/PLACARDS		
Comment:	one tank appears to not display contents/capacity. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/12/2024

**Emergency Contact Number:**

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/12/2024

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Bird Protectors	# 1					
Comment:						
Corrective Action:					Date:	
Horizontal Heated Separator	# 1					
Comment:						
Corrective Action:					Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with other tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 476282 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      WEATHER CONDITIONS: sunny, dry ground.                      On Thursday, August 29, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK TANK BATTERY (KP Kauffman Company Inc.), at location ID: 476282 in WELD COUNTY, Colorado.                      While there, I observed A SHUT IN FACILITY.                      During this inspection the following possible compliance issues were observed:                      1. It appears there is overgrown vegetation on various areas of location. Remove to comply with Rule 606. (Corrective Action Date: September 12, 2024) See attached photo #3-8.                      2. It appears the signage for the tank battery is damaged. Install sign to comply with Rule 605.e. (Corrective action Date: September 12, 2024) See attached photo #1.                      3. It appears the contents and capacity are no longer displayed on one tank. Install sign to comply with Rule 605.h. (Corrective Action Date: September 12, 2024) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	08/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201585	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688585">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688585</a>