

Operator: 8 North

Location Name: DF RANCH 1161-10-13

Loc ID: 415381

Inspection: 696300858



Exhibit A



Exhibit B

CA: Stained Soil at Engine, see photos Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

CA Resolution: Operator has properly treated or disposed of oily waste at engine in accordance with the 900 series.