

Operator: 8 North

Location Name: DF RANCH-611N61W 15NWSE

Loc ID: 410055

Inspection: 696300875



Exhibit A



Exhibit B



Exhibit C

CA: Stained Soil at Exhaust and Gas Engine, see photo 2. Corrective Action: "Properly treat or dispose of oily waste in accordance with 907.e

CA Resolution: Operator has provided photo evidence that the stained soil at exhaust and gas engine area has been addressed in accordance with the 900 series.